This Report Last Updated on: 6.15.01

NORTH ST. PAUL LIBRARY

2640 East Seventh Avenue North Saint Paul, MN 55109 Contact: Karen Byerly, Librarian 651.704.2040





Ms. Mary Sokolik, Ramsey County Library Property Manager, provided the information in this report. Mary may be reached at (651) 486-2202

SITE LOCATION

♦ SITE FEATURES

1. Overall Size: .5 Acres

2. Parking: On-Site 18 General Spaces; 1 Accessible

3. Site Description: This library sits on the eastern edge of Downtown North Saint Paul in a mixed residential/commerical area.

♦ ADJACENT LAND USES:

Single-family residential units to the immediate west and south. Commercial development along Seventh Avenue to the north. North Saint Paul historical center and commercial buildings to the east.

♦ ACCESS TO MAJOR ROADWAYS:

Seventh Avenue is the major thoroughfare running through Downtown North Saint Paul. Hwy 36 runs parallel to Seventh, approximately 2 - 4 blocks to the north. Century Avenue intersects with Seventh Avenue 2 blocks east of library.

♦ ACCESS TO PUBLIC TRANSIT:

Metro Transit Bus Route No. 9 serves this area of North Saint Paul. Also accessible via North East Suburban Transit system.

BUILDING HISTORY

♦ YEAR BUILT 1977

♦ OWNERSHIP STATUS COUNTY-OWNED
 ♦ OVERALL SIZE 10,430 Sq. Ft.
 ♦ REPLACEMENT VALUE \$ 999.669

North Saint Paul Library

PRESENT BUILDING USE

- ♦ LIST OF BUILDING TENANTS/OCCUPANTS: Ramsey County Library
- ♦ ARCHITECTURAL DESCRIPTION: Single-story slab-on-grade. Architectural brick exterior, aluminum clad skylight atrium above main entrance. Exposed wood beam ceiling on the interior.

BUILDING CONDITION SYNOPSIS

♦ ARCHITECTURAL SYSTEMS STATUS

Exterior Walls

Windows

Roof (Replaced 1995)

Interior Partitions

Flooring

Masonry

HM Frame

Good Condition

Good Condition

Good Condition

Good Condition

Good Condition

Resilient/Carpet

Good Condition

♦ ENGINEERING SYSTEMS STATUS

HVAC Includes A/C Good Condition

Fire Suppression Not Sprinkled

Plumbing Galvanized Good Condition
General Electric - Good Condition

Elevator None N/A

♦ LIFE SAFETY/ SECURITY SYSTEMS STATUS

Smoke Detectors Hard-wired Good Condition

Auxiliary Power None N/A

Security System Fire/Burglary Good Condition

♦ ACCESSIBILITY STATUS

Access to this library does not presently meet many of the ADA guidelines. However, the RC library system, as a whole, is in compliance because programs are offered at other accessible libraries.

GOOD CONDITION indicates no upgrade required FAIR CONDITION indicates significant upgrade required within 5 years POOR CONDITION indicates immediate repair or replacement is warranted

North Saint Paul Library

RECORD OF BUILDING UPGRADES & ADDITIONS

- SYSTEM UPGRADES:
 - 1995 : Roof Replacement
 - 1995: Energy Retrofit Project
 - 1995: Energy Management System upgrade
 - 1996: Window replacements
 - 1996: Telecommunications upgrade
 - 1998: Landscape improvements
 - 1998: Interior painting
 - 1998: Exterior caulking/facia painting/door & window frames painted
 - 1999: Lamp replacement
 - 2000: HVAC replacement (new rooftop units)
- ♦ ADDITIONS: None
- ♦ ALTERATIONS:
 - 1993: Parking lot overlay
 - 1995: Landscaping improvements (partial)
 - 1997: Handicap accessible power actuated door openers
 - 1997: ADA compliant Drinking Fountain (ADA Grant)
 - 1997: ADA compliant Circulation and Reference Desks (ADA Grant)
 - 1997: Cupola metal cladding project

AVAILABLE BUILDING REPORTS AND STUDIES

- ♦ Ramsey County Library: Building Condition Reports, January 1997
- ♦ Energy Audit Report: Sam Stewart and Associates, 1995
- ♦ Thermal Heat Scan Report: Thermal Sense Inc., 1995
- ♦ Roofing Report: AMBE Ltd., 1994
- ♦ Asbestos Report: 1995 Nova Environmental
- ADA Compliance Report and Transition Plan: RC Risk Management, 1997
- ♦ General Building Survey, American Testing and Engineering, 1996